


Index No. 221

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
SE 35 Corner common to sections 35, 36 W. C. 1.45CH WEST



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument W. C. Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trses

Species Y. PINE
Diameter 16"
Bearing N63W
Distance 64 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLACK
Location filed COUNTY RESURVEY "E-11"
Monument IRON MONUMENT
1918, Ben Clack Book "C" P. 296 SET IN A LITTLE POND
1919, ✓ P. 308 4x48" PAPER POST
1919, ✓ P. 315 SET 3x30" I.P. TWO W. C.
WEST 145 LKS.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CC
Washburn Lake - BK # 13 P. 38
at 5350' from E - 2" I.P. w/cap 87' N.
1940 - BK # 16 P. 8 at 2672.2' west of 5/4 - End
I.P.

Bearing Trees, Reference Objects

Species ROCK
Diameter 4.3'
Bearing S53E
Distance 66'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed MAR 2002 By LAMON - LAND DEPT
Location filed _____
Monument FOUND

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____