Index No. Z 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

SE 36 Corner common to sections 36 AND 31-139-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Bearing Trees

Species	W. PINE	ASPEN	ASPEN	ASPEN
Diameter	24"	8"	8"	4
Bearing	N49E	S5BE	S80W	N17W
Distance	48 LKS.	7 LKS	16 LKS	22 LKS.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-1"

Monument IRON MONUMENT

1918, BEN CLARK, COUNTY BOOK "C" P295 FND NE B.T. STUMP

SET 5" SPRUCE POST

1919, BEN CLARK, BOOK "C" P.314 FND POST & B.T.S. SET 3X30" I.P.

Bearing Trees, Reference Objects

Species	POPLAR	POPLAR	POPLAR	W. PINE STUMP
Diameter	8"	8"	7"	24"
Bearing	S43E	S36W	N10W	N49E
Distance	9.9'	23.9'	28.7'	31.8'
				ORIG B.T.

Evidence of Subsequent Corner Restoration

Year of search 1981 By LANDECKER

FND 2½" I.P.

MARCH 1937 CCC FND 2½" PIPE - BK#20 4

from Washburn Lake

1940 - BK 16 P.3 start N. from I.P.

Bearing Trees, Reference Objects

	BR. OAK	BR. OAK	R. OAK	R. OAK
	5"	5"	6"	8"
	N10E	N20E	S75E	S30W
	28.50'	6.04'	18.39'	38.41'

R. OAK 7" S45W 71.15'

Landecker tres

Subsequent Corner Restoration

Year surveyed 1939 By CCC

Location filed Washburn Lake - BK10. P22

Monument at 5461.7' from E - offset 146' N to iron pipe - Fnd old pine stump NE 32' marked B.T.

BK#20 - corner 1200' east of old grade.

1990 A. KERICK, CROW WING CO.

FOUND 2 1/2" IRON PIPE WITH STAMPED PLUMBERS CAP

CROW WING CO. CERT. OF LOCATION #524

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____