


Index No. 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
5/4 31 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument POST

Bearing Trees
 Species ASPEN ASH
 Diameter 11" 6"
 Bearing N80W S48W
 Distance 60 LKS 57 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1922 By BEN CLARK
 Location filed COUNTY RESURVEY "E-13"
 Monument IRON MONUMENT
1918, BEN CLARK, BOOK "C" P. 300 SET CORNER
P. 336 SET 2x48" I.P.

Evidence of Subsequent Corner Restoration
 Year of search 1939 By CC
Washburn Lake - BK # 13 P. 47
at 2423.4' from west End I.P. 5.4' N.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____