


Index No. 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 20 M. 5TH Coordinates: X _____ Y _____
SE 37 Corner common to sections 31, 32



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument Post

Species	Bearing	Trees	Y. PINE	Y. PINE
<u>FIR</u>	<u>4. PNE</u>	<u>4. PINE</u>	<u>Y. PINE</u>	<u>Y. PINE</u>
<u>8"</u>	<u>14"</u>	<u>6"</u>	<u>13"</u>	<u>13"</u>
<u>N40E</u>	<u>S60E</u>	<u>S57W</u>	<u>N53W</u>	<u>N53W</u>
<u>21 LKS.</u>	<u>6 LKS.</u>	<u>19 LKS.</u>	<u>16 LKS.</u>	<u>16 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1918 By BEN CLARK
 Location filed COUNTY BOOK C P. 291
 Monument TWO PUPPLE POST IN MOUND OF STONE AND 3 PINE STUMPS. P. 336 SET 3x30" I.P. 1922, COUNTY RESURVEY, BEN CLARK "E-13, E-14" IRON MONUMENT

Evidence of Subsequent Corner Restoration
 Year of search 1939 By CCC
Washburn Lake - BK# 13 P. 48
at 50/6' from west - Tnd 2" I.P. w/cap 11.7' N
also B.T: pine stump N7 1/2 E 8.9'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____