Index No. 27

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

5/4 32 Corner common to sections 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	W. BIRCH	MAPLE		
Diameter	6"	5"		
Bearing	N 9 E	S 8 E		
Distance	10 LKS	2 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-14"

Monument IRON MONUMENT

1918, BEN CLARK, COUNTY BOOK "C" P.303 FND POST

1919, BEN CLARK, COUNTY BOOK "C" P337-338 FND 1918 BIT

AND PINE POST SET 2½x48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK # 13 P.45

at 2651' from west - Fnd 2" I.P and 8" W.B

S 56 W 75'

Bearing Trees, Reference Objects

Species	W. BIRCH			
Diameter	13"			
Bearing	S 57 W			
Distance	75'			

1918 BIT.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____