


Index No. D-E 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 60 Corner common to sections 4, 5



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>12"</u>	<u>18"</u>	_____
Bearing	<u>S79W</u>	<u>S57 1/2 E</u>	_____
Distance	<u>11 LKS</u>	<u>24 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1934 By John Luro  
Location filed microf. film - roll 145 BK 226 P. 114-115  
Monument Find SE BIT. Standing green - plainly marked - set 2 1/4 x 30" pipe in pile of stone

Evidence of Subsequent Corner Restoration

Year of search 1981 By M. Landecker  
Found 2" iron pipe and original BT - S57 1/2 E 24 lks.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate Landecker - 1984 Doc # 276690  
Find 2" l.p. up 0.8' and orig BIT. SE  
Set 2x2x36" sq. metal post w/cap  
17" N.Pine S55E 16.37'  
S.W. Cor. cabin S15E 53.85'  
Balsam 6" S20W 29.90'  
20" w. Pine N65W 42.00'

Re monumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_