


T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 10 Corner common to sections 2, 3, 10, 11



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
 Original monument Post

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species DENSE BRUSH - NO TREE SUITABLE FOR
 Diameter BEARINGS WITHIN 15 CHAINS.
 Bearing _____
 Distance _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURIO
 Location filed COUNTY SURVEY RECORD BOOK 'BOOK' 1900-20
 Monument SET 4x4 POST PROPORTIONALLY
1920, J. FLYNN, BOOK 'C' P. 359 FND 4x6" OAK POST SET
BY CURIO - also on microfilm - roll 1125 BK 1708 P. 56
1912 - also on microfilm - roll 153 BK 271 P. 23

Evidence of Subsequent Corner Restoration

Year of search 1932 By Greene
microfilm - roll 1125 BK 196 P. 29
set l.p. from John Curio's B.T. S. S.W. Cor.
S. H. N46-05E 102.1', J. Pine 6" N82-48E 53.6'

Bearing Trees, Reference Objects

Species J. Pine N. Pine SCHOOL HOUSE ENTRANCE
 Diameter 6" 14" S.W. CORNER STAKE
 Bearing N82-48E S41-25W N46-05E
 Distance 53.60' 75.75' 102.10'

Bearing Trees, Reference Objects

1912 TIES

E-17

Subsequent Corner Restoration

Year surveyed 1981 By Landecker
 Location filed _____
 Monument Find l.p. and all ties (1 1/2" l.p. down
09' set large spike over it in road surface
5' W. of N-S Rd
10" Norway Pine WEST 42.45'
Power Pole S 30° W 42.35'
CEP S 70° E 38.20'
6" Norway Pine S 75° E 48.10'
SW Corner Foundation NE 102.10' (old tie)
NW Corner Foundation N40° E 115.45' (new)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Dave Landecker - 1986
DOC # 297695