


T. 139 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 14 Corner common to sections 11, 12, 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>BIRCH</u>	<u>WILLOW</u>	<u>OAK</u>	<u>ASPEN</u>
Diameter	<u>10"</u>	<u>30"</u>	<u>10"</u>	<u>9"</u>
Bearing	<u>N30E</u>	<u>N37 1/2 W</u>	<u>S70W</u>	<u>S35E</u>
Distance	<u>86 LKS</u>	<u>57 LKS</u>	<u>123 LKS</u>	<u>45 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 10/13/87 By Donn Basmussen  
 Found 2 1/2" iron pipe monument 18" above ground.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

<u>Norway Pine</u>	<u>Norway Pine</u>	<u>Norway Pine</u>	<u>Maple</u>
<u>18"</u>	<u>18"</u>	<u>18"</u>	<u>3"</u>
<u>S 52 W</u>	<u>N 43 W</u>	<u>N 34 E</u>	<u>S 74 E</u>
<u>92.90'</u>	<u>75.40'</u>	<u>111.00'</u>	<u>21.98'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
8-18-88 Cert Filed by Donn Basmussen  
Doc. # 306662