


Index No. R15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 27 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species BL. PINE  
 Diameter 9"  
 Bearing S 82 1/2 W  
 Distance 300 LBS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 1987 By Gary Stevenson  
Corner Certificate - Doc # 300483  
set 2X2X36" Steel post w/ aluminum cap  
at last position between MC 7 and NE 27

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  

<u>J. Pine</u>	<u>w. pine</u>	<u>J. pine</u>	<u>sign post</u>
<u>5"</u>	<u>5"</u>	<u>5"</u>	
<u>S 70 W</u>	<u>S 45 E</u>	<u>N 70 E</u>	<u>WEST</u>
<u>105.30'</u>	<u>88.60'</u>	<u>90.79'</u>	<u>1'</u>

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Gary Stevenson - 1987

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_