


T. 139 R. 29 M. 5th Coordinates: X NE 33 Y \_\_\_\_\_  
 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
 Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing Trees			
	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	24"	24"	24"	20"
Bearing	N50E	N37W	S79W	SSE
Distance	42 LKS	9 LKS	47 LKS	22 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By E. B. Horst  
 Location filed COUNTY BOOK "C" P. 350  
 Monument Find Corner  
1940, JOHN Curo, Book "D" P. 248-249 Set 248" 1/2"

Evidence of Subsequent Corner Restoration

Year of search 1968 By R. F. Schneider  
Survey for DNR - (Map in file)  
Find 2" 1/2" from old ties (below)

Species	Bearing Trees, Reference Objects			
	BIRCH	J. Pine	W. PINE	J. PINE
Diameter	6"	12"	30"	6"
Bearing	N34-29E	N52-18W	S17-55W	S47-27E
Distance	94.05'	47.15'	152.00'	63.30'

Species	Bearing Trees, Reference Objects		
	J. Pine	J. Pine	W. Pine
Diameter	6"	12"	36"
Bearing	N47E	S48E	S17W
Distance	57.30'	64.78'	152.00'

V-13

Subsequent Corner Restoration

Year surveyed 1998 By CCSO  
 Location filed CCSO  
 Monument Find 1" IP cap broken, in E Co. Rd., down 0.9'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - ADA PINE BEACH  
JOHN W. Curo 1935  
Plot - Old Point Comfort - Myron Lundcker, 1982

P. Pole, N52°E, 43.49'\*  
8" J. Pine, S75°E, 61.69'  
6" P. Oak, N55°W, 55.98'  
 \* distance to double head nail

Mar. 1918 - J. Curo, Roll 13, Bk 202, Pg 32,  
Set 2" x 20" Birch Stake from BT's

July, 1921 - E. B. Horst, Roll 12, Bk 166,  
Pg. 44, Began at 1M.

April, 1947, Roll 15, Bk 247, Pg 88,  
J. Curo set 2" x 24" Boiler tube.