


T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31- 139-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Bearing Trees			
Species <u>J. Pine</u>	<u>TAM.</u>	<u>SIRUCE</u>	<u>J. Pine</u>
Diameter <u>10"</u>	<u>4"</u>	<u>7"</u>	<u>6"</u>
Bearing <u>N18E</u>	<u>S61E</u>	<u>S80W</u>	<u>N35W</u>
Distance <u>4 LKS</u>	<u>21 LKS</u>	<u>16 LKS</u>	<u>20 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURD

Location filed COUNTY SURVEY RECORD BOOK "A" P364-368

Monument FWD 2 OLD GOVT. B.T.S: 6" J. PINE N35W 10.6', STUMP 10' J. PINE N18E 2.6' SET 2x48" CALC. CAPD ON I.P.

1922, BEN CLARK, COUNTY RESURVET "E-13"

Bearing Trees, Reference Objects

Species <u>J. Pine</u>	<u>J. Pine</u>	_____
Diameter <u>10"</u>	<u>3"</u>	_____
Bearing <u>N55E</u>	<u>N19E</u>	_____
Distance <u>68.70'</u>	<u>27.65'</u>	_____

1911 TIES

Evidence of Subsequent Corner Restoration

Year of search 1919 By BEN CLARK

COUNTY BOOK "C" P. 309 FWD CORNER.

1919, BEN CLARK, BOOK "C" P 315 SET 3x48" T.I.P

1939 - CCC - Washburn Lake BK#12 P. 35 start East from corner - B.T: 8" J. Pine N42W 28.2'

Bearing Trees, Reference Objects

<u>J. PINE</u>	_____
<u>6"</u>	_____
<u>N40E</u>	_____
<u>27.22'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Aug 1914 By _____

Twp rd order shows no survey.

May 1914; B. F. Clark

Twp rd order shows survey.