


Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X Y
E 1/4 36 Corner common to sections 36 AND 31-139-28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Aspen</u>	<u>Aspen</u>	
Diameter <u>10"</u>	<u>6"</u>	
Bearing <u>N88E</u>	<u>S85W</u>	
Distance <u>9 LKS</u>	<u>9 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-13"
Monument IRON MONUMENT
1918, BEN CLARK, BOOK "I" P. 300 SET 5x36" J. PINE POST
P. 335 SET 2x48" I.P.

Evidence of Subsequent Corner Restoration

Year of search SEPT. 2000 By CCSO
Ind. in place; 2 1/2" OD IP, diam. 0.2' in
E 48 Gravel Rd. Top is poor cond.

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>J. PINE</u>	<u>POPULAR</u>	
Diameter <u>7"</u>	<u>4"</u>	
Bearing <u>N25E</u>	<u>N45W</u>	
Distance <u>36'</u>	<u>52.5'</u>	

Bearing Trees, Reference Objects

P. Pole	Birch	CFP
<u>8"</u>		
<u>N 31° W</u>	<u>N 86° W</u>	<u>N 89° E</u>
<u>94.56'</u>	<u>82.86'</u>	<u>33.81'</u>
<u>*dist. to dbl. hd. nail</u>		

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Aug 1914 By _____
Turn rd. order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____