


Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Bearing Trees

Species	<u>N. PINE</u>	<u>Bl. PINE</u>	_____
Diameter	_____	_____	_____
Bearing	<u>N 44 W</u>	<u>N 44 E</u>	_____
Distance	<u>193 LKS</u>	<u>194 LKS.</u>	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By H. F. BALDWIN

Location filed COUNTY BOOK B P. 354-360

Monument SET 2 1/4 x 4 1/8" IRON W/ CAP PROPORTIONALLY

March 1934, Twp rd order shows no survey

Evidence of Subsequent Corner Restoration

Year of search 5/2002 By Landecker & Assoc

Found 2 1/4" Galv. iron pipe, broken top, down 2", 2 1/2" W. of 2 Co. Rd #122.

Certificate filed

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Spruce</u>	<u>R. Oak</u>	<u>"Y" Oak</u>
<u>8"</u>	<u>7"</u>	<u>12"</u>
<u>N 13° W</u>	<u>N 46° E</u>	<u>N 60° W</u>
<u>112.45'</u>	<u>96.64'</u>	<u>81.26'</u>

X-5

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - CAMP BLANCHE

JOHN CURE 1916

PLAT - HATTIE LANDING

WALTER E. CURE 1979

Remonumentation certificate prepared
Filed at CCRO document # 465200

By RLS # 21367
Date 4/17/03