


Index No. C 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 in MC# 34 Corner common to sections 2, 3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. Pine N. Pine
Diameter 20" 15"
Bearing N70E N67E
Distance 22 LKS 50 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By M.A. Kemp
Location filed _____
Monument Survey

Evidence of Subsequent Corner Restoration

Year of search 1992 By Landecker & Assoc.
Plat of LAKE VIEW OF FIVE POINT,
Doc. No. 343213, shows corner
perpetuated from 1913 survey.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

C-17

Subsequent Corner Restoration

Year surveyed 4/03 By Landecker & Assoc.
Location filed _____
Monument Found 3/4" iron pipe, RLS #21367,
Flush, 48'E N. of Lake shore.
A Cat L was filed.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

12" Oak N50°E, 72.70'
12" Spruce East, 31.11'

Remonumentation certificate prepared Doc. No. 465875 By #21367
Filed at CCRO Date 5/1/03