


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 16 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species W. Pine N. Pine \_\_\_\_\_  
Diameter 14" 7" \_\_\_\_\_  
Bearing S 59 1/2 E N 41 E \_\_\_\_\_  
Distance 25 LKS 45 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1965 By PF. Schneider  
Location filed Survey for DNR - Map in file  
Monument Found iron marker in place

Evidence of Subsequent Corner Restoration

Year of search 9/02 By Landecker & Assoc  
Found 2" iron pipe, 7" below ground, 7' ± NE of Power line. A CofL was filed.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

N. Pine R. Oak  
7" 13"  
N 18° W N 56° E  
64.20' 22.10'

E-15

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - GILLESPIE'S SUBDIVISION  
HAROLD CURD 1954

Remonumentation certificate prepared Doc. No. 465876  
Filed at CCRO

By \*21367  
Date 5/1/03