


Index No. E 18-19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
MC # 31 Corner common to sections R, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species TAm. BIRCH
Diameter 5" 14"
Bearing S48E N78E
Distance 53 LKS 93 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1987 By Dave Landerker
Corner Certificate - Doc # 298531
Find iron on N line of sec 11 and other irons
of 1925 Greene Survey. Set w/c m.c. 2" x 3/8"
sq. iron w/ aluminum cap set down 2", 33'
E. of shore

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Norway Pine</u>	<u>1 1/4"</u>	<u>S 35° W</u>	<u>48.85'</u>
<u>Norway Pine</u>	<u>6"</u>	<u>N 15° W</u>	<u>12.13'</u>
<u>Iron pipe</u>	<u>1 1/2"</u>	<u>N 8° W</u>	<u>64.95'</u>
<u>Iron pipe</u>	<u>1 1/2"</u>	<u>S 42° W</u>	<u>152.06'</u>

NE cor. cabin S 5° E 98.92'
SW cor. cabin EAST 113.30'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BRESSON'S FOUR POINT LODGE
W. J. SPAIN JR 1971 - IRON - NOT LABELED M.C.
Certificate - Dave Landerker - 1987

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____