


Index No. E19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. Pine</u>	<u>N. Pine</u>	_____
Diameter	<u>24"</u>	<u>24"</u>	_____
Bearing	<u>S 81 1/2 W</u>	<u>N 71 W</u>	_____
Distance	<u>4 LKS</u>	<u>7 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1984 By Walt Curo
Location filed Certificate
Monument End 2" x 5' capped man. lying flat under power line - set County last iron man. Flush also find remains of both B.T. stumps

Evidence of Subsequent Corner Restoration

Year of search March 1983 By Freeman - Olson
Survey Tech - Forester.
End 2" l.p. w/cap - bent over - partially out of ground w/ spike at base

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>R. oak</u>	<u>R. oak</u>
Diameter	<u>14"</u>	<u>14"</u>	<u>10"</u>
Bearing	<u>N 30° E</u>	<u>East</u>	<u>S 24 W</u>
Distance	<u>88.94'</u>	<u>44.87'</u>	<u>57.72'</u>

Bearing Trees, Reference Objects

Species	<u>R. oak</u>	_____	_____
Diameter	<u>11"</u>	_____	_____
Bearing	<u>East</u>	_____	_____
Distance	<u>45.0'</u>	_____	_____

CCLD 746.

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BRESSAN'S FOUR POINT LODGE
W.J. SPAIN JR 1971
Certificate - Walt Curo - 1984 Doc # 278539

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____