


Index No. G 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 11 Corner common to sections 11, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. Birch</u>	<u>N. Pine</u>	_____	_____
Diameter	<u>6"</u>	<u>5"</u>	_____	_____
Bearing	<u>N 30° E</u>	<u>S 75° E</u>	_____	_____
Distance	<u>7 LKS</u>	<u>19 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1987 By Dave Landecker
Location filed Corner Certificate - Doc # 298533
Monument Find 1 1/2" i.p. up 2" on E. side cleared

Evidence of Subsequent Corner Restoration

Year of search 1984 By Larry Olson
Cass Co. Land Dept.
Find 1 1/2 or 2" i.p. - painted up on top of hill

Bearing Trees, Reference Objects

Species	<u>w. pine</u>	<u>Birch</u>	<u>Redoak</u>	<u>Birch</u>	<u>Birch</u>
Diameter	<u>3"</u>	<u>4"</u>	<u>6"</u>	<u>4"</u>	<u>6"</u>
Bearing	<u>S 16° E</u>	<u>S 73° E</u>	<u>N 37° E</u>	<u>N 27° E</u>	<u>N 27° W</u>
Distance	<u>52.97'</u>	<u>5.73'</u>	<u>14.28'</u>	<u>28.93'</u>	<u>4.27'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Dave Landecker - 1987

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____