


T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument Post

Bearing Trees  
 Species N. Pine  
 Diameter 10"  
 Bearing N 50W  
 Distance 123 LKS.

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1915 By John Curo  
 Location filed COUNTY RESURVEY - "E-34"  
 Monument 2 1/4 x 4 1/8" IRON MONUMENT  
1915, GORMAN, BOOK "D" P. 41 FNO U.S. B.T. FNO 6x 6 1/2"  
TAM POST P. 45 SET 2 1/2 x 4 1/8" I.M.  
also on microf. film - roll 115 PK 79 P. 60, 64, 71-72  
P. 100. set 2 I.M.

Bearing Trees, Reference Objects  
 Species N. Pine Tam  
 Diameter orig B.T. 7"  
 Bearing NW S57W  
 Distance 17.15'

Evidence of Subsequent Corner Restoration  
 Year of search 1987 By Dave Lundecker  
Doc # 298535 - Corner Certificate  
Fnd 2" I.P. w/ 3" cap.  
100' SE of top of high mound

Bearing Trees, Reference Objects

Tam	Ash	Ash	Ash
12"	5"	7"	8"
S58°E	S55°W	N70°W	N31°W
80.06'	21.16'	42.98'	43.78'

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Lundecker - 1987