


T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
N1/4 17 Corner common to sections B, 17



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species BL Pine
 Diameter 7"
 Bearing N5E
 Distance 43 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1907 By JOHN CORD
 Location filed COUNTY SURVEY RECORD BOOK "A" P138-139
 Monument Found 7" BL Pine N5E 28.4' SET EX 80%
CEMENT POST

Evidence of Subsequent Corner Restoration
 Year of search 1967 By B. F. SCHNEIDER
SET 1/2" IRON PIPE

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
POWER POLE TELE. POLE NW CORNER
garage
NE SW SE
60.07' 53.58' 89.95'

Subsequent Corner Restoration
 Year surveyed 1924 By Miss Highway Dept.
 Location filed R/W map in Recorder's Office
 Monument Lot trap to Pine River
X on concrete monument in Q

J 7

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - R. F. SCHNEIDER - 1967
July 1919; Two rd order shows corners
previously established.