


T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Bearing Trees

Species	<u>BL. PINE</u>	<u>N. PINE</u>
Diameter	<u>8"</u>	<u>20"</u>
Bearing	<u>S 60 1/2 E</u>	<u>S 86 W</u>
Distance	<u>113 LKS</u>	<u>198 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CUPO

Location filed COUNTY SURVEY RECORD BOOK "A" P 146-147

Monument TWO OLD GOUT BITS: 8" BL. PINE S 60 1/2 E 74.6'; 20" N. PINE S 86 W 130.7'; SET 8X8X76" CEMENT POST

Evidence of Subsequent Corner Restoration

Year of search 1981 By JAMES NIELSEN/MN DOT

Found 8x8 concrete monument flush with road.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>Poplar</u>	<u>Birch</u>	<u>Jack Pine</u>
<u>6"</u>	<u>8"</u>	<u>12"</u>	<u>9"</u>
<u>N 40 W</u>	<u>N 80 W</u>	<u>S 45 W</u>	<u>N 70 E</u>
<u>73.10'</u>	<u>37.49'</u>	<u>64.84'</u>	<u>54.76'</u>

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO

Location filed file # 2000.022

Monument Monumen is gone, found 1981 witnesses NW & NE.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Nielsen - Minn DOT 1983

Doc. # 267949

L 9