


Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 24 Corner common to sections 13,24 AND 18,19- 139-29



EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species BL. PINE BL. PINE BL. PINE BL. PINE
Diameter 9" 10" 7" 10"
Bearing NR6E NR6W S80W S26E
Distance 23 LKS 25 LKS 54 LKS 15 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration
Year surveyed 1911 By HARRY S. TOOD
Location filed COUNTY SURVEY RECORD BOOK 'A' P. 373-377
Monument SET CORNER, SET 2" x 48" CAPPED GALV.
UL. IN CONCRETE
1924, GREDNE, BOOK 'D' P. 144, FIND I.M. IN ROAD

Evidence of Subsequent Corner Restoration Found
Year of search 1967 By R.F. Schneider
Survey for DNR - Map in file
Found iron marker in place
1916 - A. Nowak - microfilm - roll 1105 BK 54A P. 20
and ul. w/cap in road

Bearing Trees, Reference Objects
Species J. PINE STUMP J. PINE STUMP
Diameter 6" 12"
Bearing N64-18 E N25-28 W
Distance 24.10' 16.50'
1911 TIES

Bearing Trees, Reference Objects
1915 - M.F. Baldwin - microfilm - roll 115 BK 79
P. 123 iron monument

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search AUG. 2000 By CO SO
Find in place; 2 1/2" OD IP, diam. 0.6'
Located 1" N & St. Hwy. 87, & 24th Ave. NW
& 21' W & Rd. South.
REF. TIES:
P. Pole N 14° E 111.66' (EXIST. DOT)
19" W. Pine N 73° W 107.89' (EXIST. DOT)
16" W. Pine S 57° W 65.16' E
NE COR. OF
CONC. SLAB S 1° E 36.06'

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____