


Index No. S-T 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
MC # 17 Corner common to sections 26, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>W. Pine</u>	
<u>14"</u>	<u>12"</u>	
<u>537W</u>	<u>553E</u>	
<u>26 LKS</u>	<u>13 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1959 By Dept of Nat. Resources
 Location filed Map in File
 Monument End of Imp. 1968 TIES Below

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Species	Bearing	Trees	Reference Objects
<u>Oak</u>	<u>Birch</u>	<u>Birch</u>	
<u>6" N:BC</u>	<u>4"</u>	<u>8"</u>	
<u>West</u>	<u>South</u>	<u>East</u>	
<u>9.89'</u>	<u>1.69'</u>	<u>5.68'</u>	
	<u>N:BC W.Side</u>	<u>N:BC N.Side</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - SANBORN HEIGHTS
W.J. SPAIN 1952

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____