

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey
Year surveyed 1866
Original monument Post

Species	Bearing	Trees	ECM
<u>LINDEN</u>	<u>BIRCH</u>	<u>LINDEN</u>	<u>ECM</u>
<u>7"</u>	<u>9"</u>	<u>5"</u>	<u>5"</u>
<u>N79E</u>	<u>N29W</u>	<u>546w</u>	<u>532 1/2 E</u>
<u>24 LKS</u>	<u>31 LKS</u>	<u>9 LKS</u>	<u>12 LKS</u>

Original Evidence Found
Year of search _____ By _____
Monument found _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration
Year surveyed 1967 By R.F. Schneider
Location filed Survey for DNR - Map in file
Monument I

Evidence of Subsequent Corner Restoration
Year of search _____ By _____
June 2003 M. Landecker # 7452
Cert. of Surv. shows Mon. Found

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed Sept 2003 By M. Landecker # 7452
Location filed _____
Monument Cert of svy. shows Mon. Found

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
PLAT - HARWOOD POINT
W.J. SPAW JR. 1959

Sept 2004 R. Mustonen # 11946
Certificate of Survey shows
monument found

April 2005 T. Freeman # 21367
Cert. of Survey shows mon. found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____