


Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E/4 36 Corner common to sections 36 AND 31-139-29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Bl. Pine Bl. Pine  
Diameter 5" 5"  
Bearing N57W N42E  
Distance 13 LKS 47 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1913 By M. A. Kemp  
Location filed COUNTY SURVEY RECORDS BOOK 8 P 301-304  
Monument FIND OLD GALV BITS & 5' J. PINE N57W 13 LKS,  
5' J. PINE N42E 47 LKS. SET 39x30" T.I.M. STAKE  
1915, H. F. BALOWIN BOOK 8 P 354-360 FIND POST - CHECKS  
WITH U.S. BITS SET IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 2/2003 By Landecker & Assoc.  
Found 2 1/4" Galv. iron pipe with cap,  
up 6".  
Certificate filed.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Oak	Birch	Birch	J. Pine
7"	7"	6"	12"
N48°W	N15°E	S67°E	S80°W
29.39'	46.24'	40.44'	3.44'

X-25

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
April 1963 Rankin #921  
Cert of Survey shows monument found

Remonumentation certificate prepared   
Filed at CCRO document #465199

By PLS 21367  
Date 4/17/03