


Index No. J1

CASS COUNTY LAND CORNER RECORD

T. 139 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1860
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>SPRUCE</u>	<u>SPRUCE</u>	<u>SPRUCE</u>
Diameter	<u>10"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N40W</u>	<u>S70E</u>	<u>S45W</u>
Distance	<u>148 LKS</u>	<u>87 LKS</u>	<u>118 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P. 313-317
Monument FIND ORIG B.T.: 8" SPRUCE N40E 107.6' AND ROOTS OF OTHER B.TS. B.T. IS J. PINE
IN 1911 SET 2.48" I.P. IN CONCRETE
also on microfilm - call 115 BK 85 P. 164-165

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>J. PINE STUMP</u>	<u>J. PINE</u>	_____
Diameter	<u>3"</u>	<u>3"</u>	_____
Bearing	<u>N37-30E</u>	<u>S16-47E</u>	_____
Distance	<u>20.30'</u>	<u>12.56'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____