


T. 139 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1428 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species N. PINE N. PINE  
Diameter 20" 15"  
Bearing N 88 1/2 E S 65 1/4 W  
Distance 10 LKS 30 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration

Year surveyed 1915 By SCOTT  
Location filed COUNTY BOOK 'D' P. 11  
Monument FIND BIRTH GOVT B.T.S. SET CORNER  
ALSO ON MICROFILM - ROLL 105 BK 67 P. 13

Evidence of Subsequent Corner Restoration

Year of search 8/2/1983 By Freeman - Olson  
SurveyTech - Forester  
Eng 2" O.D. 1 1/2" w/cap 4 1/2" long 3 1/2" out  
of ground also find orig B.T. Stamps.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

N. Pine N. Pine  
21" 20"  
N 50 W N 40 E  
36.00' 30.7'

*C.C. Land Dept tag*

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Cura - 1985  
set 2" Sq. iron w/stamped aluminum cap  
4" W. Pine - N 38° E 14.70'  
4" W. Pine - S 89° E 26.92'  
4" Maple N 77° W 10.13'  
Doc. # 281876.