


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Certificate of Location of Government Corner filed in Cass County

By _____


Recorders Office as Document _____

Date _____

Index No. ER3

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 112



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>BL. ASH</u>	<u>BL. ASH</u>	
<u>5"</u>	<u>5"</u>	
<u>N 16 1/2 E</u>	<u>S 22 E</u>	
<u>14 LKS</u>	<u>14 LKS.</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD Book A' P552-555
Monument SET PROPORTIONALLY

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 4 P. 19
Set approx 1/4 Post at 2640 from east

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>CEDAR</u>	<u>6"</u>	<u>N 30 E</u>	<u>3.90'</u>
<u>CEDAR</u>	<u>8"</u>	<u>SSE</u>	<u>4.50'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____