


T. 140 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 10 Corner common to sections 10, 11



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1867

Original monument Post

Species	Bearing	Trees
<u>Aspen</u>	<u>BIRCH</u>	
Diameter <u>10"</u>	<u>4'</u>	
Bearing <u>S 61 3/4 W</u>	<u>54 3 E</u>	
Distance <u>10 LKS</u>	<u>19 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**

Year surveyed 1905 By C. Taylor

Location filed Twp. Road Orders

Monument Surveyors Report indicates corner post.

**Evidence of Subsequent Corner Restoration**

Year of search Sept. 1910 By M. Watson

Twp rd order shows rd on E 1/4 line

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

G-17

**Subsequent Corner Restoration**

Year surveyed 1905 By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Gary Stoverson - 1984  
Doc. # 275706  
Set cast iron monument at intersection of roads. Ties: 14" Spruce? N 30 W 104.23'; Power Pole N 50 E 56.82'; 8" Aspen S 10 E 57.94'.

1998 - CCSO Found CIM, down 0.6' in & added nails to 1984 witnesses.

14" Balsam, N 15 W, 104.19 \*  
11" Aspen, S 7 E, 57.88 \*  
4" Maple, S 41 W, 94.88 \*  
P. Pole, N 53 E, 56.73 \*  
\* distance to double head nail