


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. L 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 14 Corner common to sections 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species ASPEN ASPEN
Diameter 10" 10"
Bearing S42E S83W
Distance 16 LKS 4 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed June 2001 By Land Dept - A.R.J.
Location filed _____
Monument Found 1" pipe down 6" on E side of road.

Evidence of Subsequent Corner Restoration

Year of search Mer 2001 By C. S. L. Lewelling
Cert. of svy shows mon. Found.

Bearing Trees, Reference Objects

Species Witch Birch
Diameter _____
Bearing SE West
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

L-21

Subsequent Corner Restoration

Year surveyed 1905 By C. Taylor
Location filed Twp. Road Orders
Monument Surveyors Report indicates corner post.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____