

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	W. PINE	W. PINE	W. PINE	W. PINE
Diameter	<u>10"</u>	<u>8"</u>	<u>5"</u>	<u>8"</u>
Bearing	<u>S19E</u>	<u>N70W</u>	<u>N78E</u>	<u>S76W</u>
Distance	<u>31 LKS.</u>	<u>5 LKS</u>	<u>40 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - Bk# 3 P. 20
Monument Start at approx corner

Evidence of Subsequent Corner Restoration

Year of search June 2001 By Land Dept. - A.R. J.L.
Found 1" pipe RLS 16089

Aug. 1911 M. Watson
Twp road order shows survey

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>Maple</u>	<u>W. Oak</u>	_____
<u>w</u>	<u>w</u>	<u>East</u>	_____
_____	_____	_____	_____
_____	_____	_____	_____

N-21

Subsequent Corner Restoration

Year surveyed 1905 By C. Taylor
Location filed Twp. Road Orders
Monument Surveyors Report indicates corner.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1911, M. Watson, Twp. Road order,
Surveyors Report indicates road
on section line.

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____