


Index No. N23

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
N14 24 Corner common to sections 13, 24



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument EST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SPRUCE SPRUCE _____
Diameter 4" 4" _____
Bearing NE NW _____
Distance 8 LKS 10 LKS. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1911 By M. Watson
Location filed Twp. Road Orders
Monument Surveyors Report indicates road on Section line.

Evidence of Subsequent Corner Restoration

Year of search March 2002 By E. Lindquist Cass Co. Land Dept.
Found pipe approx 5" up capped with NLSM LS 16089
Fieldgrade GPS Location N 5197990 E 440223

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____