


Index No. R 11

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Distance
<u>MAPLE</u>	<u>ASpen</u>		
<u>5"</u>	<u>6"</u>		
<u>N 1/8 E</u>	<u>S 1/8 W</u>		
<u>10 LKS</u>	<u>17 LKS</u>		

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - Bk# 3 P. 17
Monument at 2640' from west - set approx corner

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____