Index No. <u>R.0-21.0</u>	<u>) </u>	CASS COU	UNTY LAND	CORNER I	RECORD			-
T. <u>140</u> R. <u>25</u>	M. 5th	ordinates. Y		v				
NE 26	Corner common to sec			'_				
		,					2	6
			EXISTING					
V	Original Government	Survey		Original Evidence Found				
Year surveyed 1867				Year of search 1920 by Horst				
Original monument Post				Monument t		no== 50 1		- Cor
	Bearing Trees			Jourvey R	ec 480, Bk C, Origin	page 531 nal Bearing Trees		= Corner
Species W. B			Acnon	Species		_		
Diameter 18	irch Aspen " 5"	Fir 4"	Aspen 5"	Diameter				
Bearing N 49			S 38° W	Bearing				
Distance 14 lii		12 links	14 links	Distance		,	·	
			Evidence of	Subsequent Corne				
		M. Watso	on	'II	rch <u>11/1920</u>		E.B. Horst, LS	
	oky Hollow Townshi	p Road Order		II	-	cord #480, Boo	ok C, page 53′	1 and Curo
Monument: Indicates road or	section line			Monument:		3		
Indicates road on section line.					ok 68, page 49 tersection wh	9 ere I saw the s	tump of one of	f the orig
				U.S. BTs	before the ro	ad running S. v	was constructe	ed. The
Bearing Trees, Reference Objects						ed out I set po Bearing Trees, Re	oint at P.I. of R	
Species	beaming frees, h	Colorelice Objects		Species	Tal Dala	_	-	
Species				Species Diameter	Tel Pole			
Bearing				Bearing		SW corner N 49°53' E		
Distance				Distance	32.8'			
		· ———			<u> </u>	100.4		
	Subsequent Corner Res				Evidence of Sub	sequent Corner R	Restoration Found	
		J. Curo, LS	1428	Year of sea	rch	Ву		
	o Book 152, page 5	5	_ -	Location file	ed:	_ -	_ -	_ -
Monument:		\ 7 ' · ·	. 400-	Monument:				
Indicates N. line witnesses.	of Section 26 at 529	<i>er</i> and lists th∈	9 1920					
1937, CCC	300k 4 no 10							
Washburn Lake I indicates cor 17'	Book 4, page 12 east of center of roa	ad.						
	J. Joiner of 10(
1/2006, CCHD/S	0							
#2004.011 Set 1.12" ODIP (down 0.2', at record	hearing and d	listance					
	oown 0.2°, at record of stone School four		notal IUC					
IP set at SW corr	ner of School Found		'E, 160.40'					
8" Elm, N 11° E,								
6" Ash, N 47° W, 11" Basswood, S								
	,							
				<u></u>				
Certificate of Location	n of Government Corner	filed in Cass Cour	nty	Ву		T.L. Freeman.	LS 21367	
Recorders Office as Document A000656255				Da	te		9/2019	

Index No. R Z/ CASS COUNTY LAND	CODNED DECODD
Index No. 🔨 / CASS COUNTY LAND	CORNER RECORD
140 DK K_1	
T. 1 10 R. 25 M. 57H Coordinates: X	YY
T. $140 R$ $25 M$ $57H$ Coordinates: X $N \in R G$ Corner common to sections $R3,24,25,27$	
	! 0 (
EXISTING	SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 1867	Year of searchBy
Original monument Post	Monument found
Begring Trees	Original Bearing Trees Found O = Corner
Species W. BIRCH ASPEN FIR ASPEN	Species
Diameter 18" 4" 4" 5"	Diometer
Bearing N49E 5/1E N40W 538W	31
Bearing 11 tes 9 tes 17 tes 11 tes	Bearing
Distance 14 LKS 9 LKS 12 LKS 14 LKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1920 By E.B. Horst	Year of search 1937 By CCC
Year surveyed 1920 By E'B. HORST Location filed COUNTY BOOK C 8531	Year of search 1937 By CCC Washburn Luke - BK#4 P.12
Monument SET CURNIN AT ROAD INTERSECTION WHORE	Cor 17' east of center ofroad
Port For For AT Con A Co	
CONT FALLS FROM OLD B.T STUMP (NOW CONE)	
T. 1100 0010 0 10 =	
also on microf.lm - roll 105 BK68 P. 49-50	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species S.W. LORMER TELE. POLE POPLAR	
Diameter ScHool House 8"	
Bearing <u>N49-53 ε</u> <u>N 47-3οω</u> <u>S53-45 ε</u>	
Bedring 747-55 777-56 355-458	
Distance 160,4' 32.8' 70.8'	
	<u> </u>
P-21	Mir
R-21 Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found Year of search By
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Leasting filed Two Road Orders	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Leasting filed Two Road Orders	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates road on Section Irne.	Year of search By
Subsequent Corner Restoration Year surveyed 1911 By M. Watson Location filed Twp. Road Orders Monument Surveyors Report indicates	