


T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey			
Year surveyed <u>1867</u>			
Original monument <u>Post</u>			
Bearing Trees			
Species <u>B. OAK</u>	<u>B. OAK</u>	<u>MAPLE</u>	<u>BIRCH</u>
Diameter <u>12"</u>	<u>8"</u>	<u>5"</u>	<u>10"</u>
Bearing <u>N 53 1/2 W</u>	<u>S 53 W</u>	<u>N 20 E</u>	<u>S 28 E</u>
Distance <u>39 LKS</u>	<u>22 LKS</u>	<u>14 LKS</u>	<u>42 LKS</u>

Original Evidence Found	
Year of search _____	By _____
Monument found _____	
Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration			
Year surveyed <u>1916</u> By <u>E. B. Horst</u>			
Location filed <u>County Book C P. 535</u>			
Monument <u>FWO. Cut Bit: 12" B. OAK N 53-30W 39'</u>			
<u>SET Post</u>			
<u>also on microfilm - roll 105 BK 68 P. 4, P. 30</u>			
<u>Set I. M.</u>			
Bearing Trees, Reference Objects			
Species <u>BASSWOOD</u>	<u>W. PINE SWAMP</u>	<u>MAPLE</u>	<u>W. PINE SWAMP</u>
Diameter <u>10"</u>	<u>18"</u>	<u>5"</u>	<u>30"</u>
Bearing <u>N 24 E</u>	<u>N 67-30W</u>	<u>S 46-30W</u>	<u>S 62-30E</u>
Distance <u>31.0'</u>	<u>44.1'</u>	<u>56.2'</u>	<u>58.0'</u>

Evidence of Subsequent Corner Restoration	
Year of search <u>1937</u>	By <u>CCC</u>
<u>Washburn Lake - Bk # 3 P. 16</u>	
<u>at 5200' from west - Set Approx Corner</u>	
Bearing Trees, Reference Objects	
_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration	
Year surveyed <u>1911</u>	By <u>M. Watson</u>
Location filed <u>Twp. Road Orders</u>	
Monument <u>Surveyors Report indicates</u>	
<u>road on N-S section line.</u>	

Evidence of Subsequent Corner Restoration Found	
Year of search _____	By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____