


Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
E114 31 Corner common to sections 31, 32 W.C. 100 CH SOUTH



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument POST W.C. 1 CH. SOUTH

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO TREE NEAR
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1911 By M. Watson
Location filed Twp. Road Orders
Monument Surveyors Report indicates road on E-W 1/4 line.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____