


Index No. X 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E/4 32 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species FIR FIR  
Diameter 8" 6"  
Bearing S95E S55W  
Distance 10 LKS 10 LKS.

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - PK#2 P. 12  
Monument Set 3' oak stake approx cor. 40 CH from South

Evidence of Subsequent Corner Restoration

Year of search 1911 By M. Watson  
Tap. Road Order, Surveyors Report indicates road on E-W 1/4 line.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_