


Index No. C 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 5 Corner common to sections 4,5



○ = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1871  
Original monument Post

Species	Bearing	Trees
<u>CEDAR</u>	<u>CEDAR</u>	
Diameter <u>9"</u>	<u>6"</u>	
Bearing <u>N 24E</u>	<u>S 62W</u>	
Distance <u>10 LKS</u>	<u>8 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1936? By CCC  
Location filed Washburn Lake - BK # 3 P. 52  
Monument Scribed stake

**Evidence of Subsequent Corner Restoration**

Year of search 1910 By CUVO  
microfilm - roll 115 BK 91 P. 11  
Find SW B.T. standing green - set true  
1/4 corner

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_