


T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 10 Corner common to sections 2,3,10,11



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Notes show POND 0.13 chains west; 0.16 chains north

Species	Bearing Trees			
	ASH	ASPEN	FIR	FIR
Diameter	6"	7"	12"	8"
Bearing	N74E	N87W	S76W	S25E
Distance	16 LKS	19 LKS	14 LKS	18 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1941 By JOHN CURO

Location filed COUNTY BOOK "D" P. 253

Monument 2x3" I.P.

1937 - CCC - Washburn Lake - BK #5 P. 35

Start west from approx cor

1937 - BK # 6 P. 6 at 5280' from east set app cor.

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	BL. ASH	POPLAR	ELM
Diameter	12"	14"	14"
Bearing	N63-10E	S67-25E	S43-50W
Distance	35.65'	25.62'	15.12'

1941 Curo Ties

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker

Found 2" iron pipe up 18"

Dead 24" Elm N 68 E 92.3' (1965 BT); Dead

24" Elm N 85 W 12.9' (1965 BT).

Bearing Trees, Reference Objects

Ash	Ash	Ash	Ash
7"	6"	5"	8"
N 74 W	S 53 W	S 52 E	N 72 E
7.68'	42.03'	14.39'	4.70'

E-17

Subsequent Corner Restoration

Year surveyed 1965 By R. F. Schneider

Location filed _____

Monument Found 2" Iron Pipe

Ties: 24" Elm N85W 10.9

BOOK D } 6" Ash East 4.5

P. 455 } 24" Elm N68E 92.3

Stamp S47W 15.4'

1971 - Don Coulter - fcl. pipe from Schneider ties.

Ties: SW Cor House N79-15E 161.95

16" Ash S84W 10.9

12" Ash S64-15W 15.0

10" Poplar S22-30W 32.65

E - 17

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Cert Filed by David Landecker

Doc. # 317222

April 2005 J. Bunkowski #24606

Cert. of Survey shows monument found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____