


T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees		
Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>3"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>N14W</u>	<u>N7E</u>	<u>S34E</u>
Distance	<u>12 lks</u>	<u>13 lks</u>	<u>23 lks</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By Green
Location filed Plat of OAK LAWN BEACH
Monument Ivan monument set from original evidence
1910-Curo-Microfilm-Roll 105 BK48 P.50
End all 3 B.T.S

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC BK# 20 P. 25
Found 1. Pipe buried under road center
BK# 5, P. 39 - 1937 - Ties below
back from Washburn Lake

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Bl. Spruce</u>	<u>Bl. Spruce</u>	<u>Bl. Spruce</u>	<u>Spruce</u>
<u>N48 1/2 E 5'</u>	<u>6"</u>	<u>6"</u>	<u>6' (long ground)</u>
<u>N48 1/2 E</u>	<u>S39 1/2 E</u>	<u>S21 W</u>	<u>N69 1/2 W</u>
<u>25.4' 24.5'</u>	<u>35' 34.6</u>	<u>39.5' 40'</u>	<u>37'</u>
<u>scribed</u>	<u>scribed</u>	<u>scribed</u>	<u>scribed</u>

E-5

Subsequent Corner Restoration

Year surveyed 1979 By G.H. Stevenson
Location filed _____
Monument Found 1" iron pipe down 0.1' and
3' West & N-S road. Pipe had been
set by T. Kavack over found 1. m.
Found remains of stump with scrubby
S 25 W 36' ± and remains of stump
N 53 E 28' ± - these are remains of
the CCC ties.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - OAK LAWN BEACH
JOHN M. GREEN 1972

1985 - Stevenson - Dug 4' down and find top
of 2" capped l.p. set cast iron over 1 1/2"
Corner is 6' W. of approx & N-S Rd, 14' N.
of power line clearing
12" Tam S 80° W 90'
18" Tam S 30° W 28.62'
5" Tam S 30° E 76.33'

Certificate - Gary Stevenson - 1987
Doc# 295 281

March 2005 T. Freeman # 21367
Cert. of Survey shows monument found

May 2005 T. Freeman # 21367
Cert. of Survey shows monument found