


T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Y. BIRCH</u>	<u>555W</u>	<u>W. BIRCH</u>
<u>8"</u>	<u>570E</u>	<u>W. PINE</u>
<u>29 LKS.</u>	<u>75 LKS.</u>	<u>30"</u>
		<u>108 LKS.</u>
		<u>N4E</u>

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? By Geo. A. Ralph  
 Location filed County Survey Record Book "B" P. 88-89  
 Monument SURVEY OF STATE RURAL HWY # 83  
TIES - SEE BOOK "B" P. 88-89  
1941, JOHN CRO, BOOK "D" P. 253 2 1/4 x 26" I.P.  
1953, H. CUND, BOOK "D" P. 424 FND 1941 TIES EXCEPT SW

Evidence of Subsequent Corner Restoration

Year of search 1936 By CCC  
Washburn Lake - BK #3 P. 48  
Section corner  
1937 - CCC - Washburn Lake - BK #6 P. 2  
at 52.60' from east - set approx sec. cor 25'  
from center of Hwy 6

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>PIPE (WITNES)</u>	<u>N45E</u>	<u>46.67'</u>
<u>W. OAK</u>	<u>515-04E</u>	<u>152.65'</u>
<u>N. PINE</u>	<u>57-14W</u>	<u>332.55'</u>
<u>N. PINE</u>	<u>N40-19W</u>	<u>91.90'</u>

Bearing Trees, Reference Objects

1941 TIES

Subsequent Corner Restoration

Year surveyed 1970 By RF Schneider  
 Location filed \_\_\_\_\_  
 Monument: Found Pipe

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1965 - R.F. Schneider set 1" iron pipe from old ties.

1989 Cert. Filed by David Landecker Doc. # 317224.

~~Ties: 20" W. Oak S38W 64.5  
 2" N. Pipe S65W 37.4  
 P.P. N61W 41.5  
 Maple stump N53 1/2 W 91.5  
 corner in E of N-S road  
 E road East 14.8 North~~

Found County cast iron monument 12" below road surface. Set 3/8" x 8" rerod over found monument. TIES: 24" Norway Pine N35W 92.69' (1941 BT); 7" Burr Oak S34W 85.84'; 1 1/2" iron pipe N50E 46.57' (1941 BT); Power pole S37E 48.00'.

Ties: 15" W. Oak S10E 152.05  
20" N. Pine N15W 91.9  
2" Pipe N45E 46.67'  
in E N-S road } Book "D" P. 455

1999 - Levelling #16089 - Certificate of Survey indicates position.

corner GPS CCSO 8/14/02  
CCSO fdr. clin, down 1.3', 2' ± E, of E

20" N. Pine N35W 92.69'  
8" W. Oak S34W 85.84'  
P-pole S47E 48.00'  
Survey Marker sign, West 21.0'