


T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 13 Corner common to sections 12, 13 AND 7, 18-140-25



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1864  
Original monument POST  
Notes show leave Spruce Swamp at corner

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

|  | Bearing Trees |                 |               |               |
|--|---------------|-----------------|---------------|---------------|
|  | Species       | Diameter        | Bearing       | Distance      |
|  | <u>Poplar</u> | <u>W. Birch</u> | <u>Poplar</u> | <u>Poplar</u> |
|  | <u>10"</u>    | <u>7"</u>       | <u>9"</u>     | <u>9"</u>     |
|  | <u>N 65 E</u> | <u>N 53 W</u>   | <u>S 80 W</u> | <u>S 60 E</u> |
|  | <u>29 lks</u> | <u>13 lks</u>   | <u>12 lks</u> | <u>8 lks</u>  |

| Original Bearing Trees Found |          |         |          |       |
|------------------------------|----------|---------|----------|-------|
| Species                      | Diameter | Bearing | Distance |       |
| _____                        | _____    | _____   | _____    | _____ |
| _____                        | _____    | _____   | _____    | _____ |
| _____                        | _____    | _____   | _____    | _____ |
| _____                        | _____    | _____   | _____    | _____ |

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washington Lake - BK # 2 P. 69  
Monument at 5118' from east For d. l. P. 335' N.  
Yellow tag on tree (Aspen) 70' N i 70' E.  
BK # 4 P 30 - 1937 - started N. from iron pipe

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_