


T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>N. Pine</u>	<u>10"</u>	<u>10"</u>	<u>8"</u>
<u>N39E</u>	<u>55W</u>	<u>N33W</u>	<u>57E</u>
<u>18 lks</u>	<u>42 lks</u>	<u>12 lks</u>	<u>50 lks</u>

Original Bearing Trees Found

Species	Bearing	Trees	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1910 By John Curo
Location filed Book A, p. 312
Monument Set wood stake from stumps
of SE and SW - 6LO BTs

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC BK# 20 P. 36
Found 2" iron pipe and scribed stake
Washburn lake

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Aspen</u>	_____	_____	_____
<u>8"</u>	_____	_____	_____
<u>S64E</u>	_____	_____	_____
<u>12.7'</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By P.F. Schneider
Location filed _____
Monument Found 1 1/2" galv. iron pipe and
12" N. Pine stump with bottom
blaze NW 11.5'
Old fence lines north & east

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1987

1980 - G.H. Stevenson
Ed. iron pipe

Ties: 12" N. Pine N70W 84.58
6" R. Oak N5W 31.62

1983 - Gary Stevenson - replaced found iron w/
cast iron. NW B.T. still evident

Certificate - Doc # 295286
12" N. Pine N72°W 84.50'
7" Red oak N11°E 31.62'
5" Maple N59°E 16.50'
remains of fence N & E

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____