


T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
N 14 17 Corner common to sections 8, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Species	Bearing	Trees
<u>N. Pine</u>	<u>N. Pine</u>	
<u>6"</u>	<u>6"</u>	
<u>N88W</u>	<u>S74E</u>	
<u>5 lks.</u>	<u>10 lks.</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC BK#20 P.36
Ed scribbled stake and BITS below
BK #6 P.34 Find stake at 1305' from w/116
Washburn Lake

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. Pine</u>	<u>W. Pine</u>		
<u>10"</u>	<u>6"</u>		
<u>S16E</u>	<u>N32W</u>		
<u>20.8'</u>	<u>6.8'</u>		

BK#20 CCC

Subsequent Corner Restoration

Year surveyed 1966 By R. F. Schneider
Location filed _____
Monument Found 4" Hewed wood post scribbled
" 145" - Set 2'4" x 36" iron pipe
in hole of post.

Ties:

- 15" N. Pine N20W 5.65' (old blazes)
- 6" N. Pine S31E 16.25'
- 8" N. Pine S27W 7.95'

1979- G.H. Stevenson

Ed pipe set by Schneider

Ties:

- 18" N. Pine N20W 6.23' - spk
- 20" N. Pine N35E 17.92' - ✓
- 10" N. Pine S31E 16.35' - ✓
- 10" N. Pine S27W 8.05' - ✓

Pine Stump S15E 20.4' (CCC)

1983- GHS replaced I.P. w/ cast iron monument
same ties as 1979 - Certificate - Doc # 295287

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - PINWOOD ~~SHADOWS~~ SHADOWS
R.F. SCHNEIDER 1967

Certificate - Gary Stevenson - 1987

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____