


Index No. J 7-8

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
M.C.# 20 Corner common to sections 8, 17

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. Pine
Diameter 20"
Bearing West
Distance 50 lks.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC BK#20 P. 36
Found scribbled stake washburn lake
at 16.6' from W 1/4 scribbled stake BK#6 P. 34

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Aspen
8"
S20E
7.8'
BK#20

Subsequent Corner Restoration

Year surveyed 1966 By R.F. Schneider
Location filed _____
Monument Found 1 1/2" Iron Pipe in place

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - PINWOOD SHADOWS
R.F. SCHNEIDER IRON - NOT LABELED M.C.1979 - G.H. StevensonFd. pipe in place as found by Schneider
and also found large badly rotted
pine stump 34'± west of the
pipe that I believe is remains of
original B.T.

Ties:

13" R. Oak N40W 15.0' - center
14" Poplar S60W 19.6' - ✓
6" Elm S12E 14.04' - spk
8" Elm S60E 26.01' - spk

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____