


Index No. R9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X NE 29 Corner common to sections 20, 21, 28, 29 W.C. 1.00 CH. SOUTH



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post W.C. 1.00 CH SOUTH
Corner in Pond

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. Pine N. Pine _____
Diameter 10" 8" _____
Bearing S16E S86W _____
Distance 24 LKS 18 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK#6 P.19
Monument at 52.80' from E. - SET approx cor.
1937 - BK#6 P.24 - Start W. from Approx Cor.

Evidence of Subsequent Corner Restoration

Year of search 1981, 1986 By Bert EVELAND - DNR
Corner Certificate - Doc # 297689
End remains of 1 6' 0" BT
set 1 1/2" x 2 1/2" 1IP.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Maple	Maple	Roak	Birch
<u>11"</u>	<u>8" x 12"</u>	<u>7"</u>	<u>11"</u>
<u>N75W</u>	<u>N63W</u>	<u>S25E</u>	<u>N40E</u>
<u>58.56'</u>	<u>10.24'</u>	<u>23.57'</u>	<u>1.89'</u>

R-9

Subsequent Corner Restoration

Year surveyed MAY 2000 By F. SIORBA - PVT FORESTER
Location filed STR FILE - CCSO
Monument NO RECOVERY

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - DNR - Bert EVELAND - 1986

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____