


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5th Coordinates: X _____ Y _____
N 114 33 Corner common to sections 20, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. Pine</u>	<u>W. Birch</u>	_____	_____
Diameter	<u>16"</u>	<u>10"</u>	_____	_____
Bearing	<u>N 79 E</u>	<u>S 87 W</u>	_____	_____
Distance	<u>24 LKS</u>	<u>35 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CC
Location filed Washburn Lake - BK # 5 P. 17
Monument at 2640 from East - set approx 1/4 cor.
1987 W. Buckler set 3/4" iron pipe
at lost position.

Evidence of Subsequent Corner Restoration

Year of search Mar 1999 By C.C. Land Dept. - A.R. J.L.
Found 3/4" pipe, 6" above ground
RLS 9672

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

V-11

Subsequent Corner Restoration

Year surveyed 9/03 By Landecker & Assoc
Location filed _____
Monument Found 3/4" iron pipe capped
RLS 9672 and witnessed.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

W. Pine 26" N 30°W 33.42'
R. Oak 7" N 67°E 25.76'
A cot L was P. led.

Remonumentation certificate prepared #474532
Filed at CCRO

By #21367
Date 10/7/03