


Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post
Notes show Pond 2.72 chains east

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	W. Oak	W. Oak	W. Pine
Diameter	<u>8"</u>	<u>8"</u>	<u>26"</u>
Bearing	<u>S68W</u>	<u>N73W</u>	<u>S2E</u>
Distance	<u>68 lks</u>	<u>34 lks</u>	<u>128 lks.</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK#1 P.56
Monument Set App. Cor. 3" oak w/ yellow tag
at 5249.5' from
BK#2 P.37 4" oak post 5275' from east

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____