


T. 146 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 B Corner common to sections 5, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Species	Bearing	Trees
<u>Poplar</u>	<u>Poplar</u>	
<u>4"</u>	<u>10"</u>	
<u>N 25 E</u>	<u>S 45 W</u>	
<u>12 LKS</u>	<u>12 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1975 By Walt Curo
Set cast iron monument 4" dia. top x 20" long, 4" below surface of Twp. Road.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Power Pole	Birch	Birch	Birch
	<u>8"</u>	<u>8"</u>	<u>8"</u>
<u>N 61° 35' W</u>	<u>S 61° 03' W</u>	<u>N 08° 43' E</u>	<u>S 28° 33' E</u>
<u>48.72'</u>	<u>11.45'</u>	<u>55.35'</u>	<u>12.59'</u>

E - 7

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BIRCHWOOD SHORES
JOHN W. Curo 1949

CERTIFICATE - WALT Curo - 1975
Doc. # 223885

Sept 2002 P. Blethen # 17367
Cert. of Svy. Shows Mon. Found

Dec 2002 L. Leuelig # 16089
Cert. of Svy. Shows Mon. Found

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____