


Index No. G 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>TAM.</u>	<u>TAM.</u>
Diameter <u>7"</u>	<u>6"</u>
Bearing <u>N48-30W</u>	<u>N41E</u>
Distance <u>6 LKS</u>	<u>30 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1906 By John Curo  
Location filed COUNTY SURVEY RECORD BOOK "A" P 308312  
Monument END OR 16 POST & ORIG BITS

Evidence of Subsequent Corner Restoration

Year of search 1913 By \_\_\_\_\_  
CO DITCH SURVEY BK 9 BOX 2 OF CO  
DITCH SURVEY BOOKS, PL 51

Bearing Trees, Reference Objects

Species <u>TAM</u>	<u>TAM</u>
Diameter <u>7"</u>	<u>6"</u>
Bearing <u>N48-30W</u>	<u>N41E</u>
Distance <u>4.0'</u>	<u>19.8'</u>

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_